



MICHIGAN DEPARTMENT OF
ENVIRONMENT, GREAT LAKES, AND ENERGY

March 12, 2026 CAG Meeting

House Street

- Regular inspections of capped areas
- Monitoring vegetation growth
- Erosion issues outside of the capped areas that are being addressed this week



Tannery


- Interceptor system continues to run regularly
- Recently changed out the first trailer of carbon vessels for the filtration system
- GZA continues to tweak the system to try to meet the metrics from the Response Activity Plan
 - They're not currently meeting the metrics for every trench
- Wolverine has until March 2027 to meet the metrics or propose changes to the system



LEGEND

Sampling Locations

- Permanent Piezometer
- Monitoring Well
- VAP/Monitoring Well
- VAP
- Soil Borings
- Surface Water Samples
- Soil Boring/Temporary Well
- Sewer and Water Lines - Field Measured
- Gravity Unknown Diameter
- Gravity 8" Diam
- Gravity 10" Diam
- Gravity 12" Diam
- ▭ Sole Plant Property Boundary
- ▭ Approximate Parcel Boundaries



Sole Plant

- In January, EGLE received results from an investigation Wolverine did along the sewer line
- GZA is preparing a summary of that investigation for EGLE review
- Next steps will be proposed in a separate work plan

Courtland & 11 Mile

- Wolverine submitted a Response Activity Plan for drilling at two off-site locations
- Drilling is being conducted this week
- Additional work will be needed after this round of drilling

